Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	57299	(plural\$4 several array two second couple multiple ) near3 (pressure force load strain stress ) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:43
L2	1912	1 and (plural\$4 several array two second couple multiple ) near3 (pressure force load strain stress ) near3 (duct port )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:44
L3	246	2 and (brak\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:37
L4	166	3 and (hydraulic )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:55
L5	26	4 and (flange )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:37
L6	22	5 and (housing casing frame )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:37
L7	10	6 and (nut bolt fasten\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:49
L8	0	"58877851"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON .	2006/12/02 10:39
L9	4	"5887851"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:47

12/2/06 11:06:04 AM Page 1

	·	Y-1				
L10	6	("5226221"   "5331730"   "5423117"   "5533249").PN. OR ("5887851").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/02 10:48
L11	. 2	9 and (nut bolt fasten\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:42
L12	105	(electrohydraulic ) near3 (brak\$4). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:43
L13	4	12 and (plural\$4 several array two second couple multiple ) near3 (pressure force load strain stress ) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:43
L14	883	(electrohydraulic ) near3 (brak\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:43
L15	53	14 and (plural\$4 several array two second couple multiple ) near3 (pressure force load strain stress ) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:45
L16	3	15 and (plural\$4 several array two second couple multiple ) near3 (pressure force load strain stress ) near3 (duct port )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:44
L17	361	73/121.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:44
L18	33	17 and (plural\$4 several array two second couple multiple ) near3 (pressure force load strain stress ) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:45
L19	16	18 and (hydraulic )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 10:46

12/2/06 11:06:04 AM Page 2

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1164	(plural\$4 array couple multiple two second several ) near3 (pressure force load stress strain ) near3 (sens\$4 detect\$4 transducer measur\$4 cell gage gauge ) near3 (housing casing frame )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:11
L2	44	1 and (hydraulic ) near3 (casing housing frame )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:10
L3	25	2 and (duct port )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15
L4	11	3 and (flange )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:10
L5		4 and (fasten\$4 nut bolt screw )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15
L6	11	4 and (fasten\$4 nut bolt screw connector connection )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:11
L7	63669	(plural\$4 array couple multiple two second several ) near3 (pressure force load stress strain ) near3 (sens\$4 detect\$4 transducer measur\$4 cell gage gauge )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:12
L8	8266	7 and (sens\$4 detect\$4 transducer measur\$4 cell gage gauge ) near3 (housing casing frame )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15
L9	219	8 and (hydraulics) near3 (housing casing frame )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15

12/2/06 11:17:39 AM Page 1

L10	219	8 and (hydraulic) near3 (housing casing frame )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15
L11	70	10 and (flange )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15
L12	38	11 and (duct port )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15
L13	36	12 and (fasten\$4 nut bolt screw)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/02 11:15

Page 2